



FIG.2





FIG. 3


FIG.3




4/26

FIG.4


(TH FIRST BAND)




(TH SECOND BAND)



(TE FIRST BAND)



0-



0 -




FIG.6




FIG.7




FIG.8






FIG.9





FIG.10






FIG.12





FIG.13



094663-11501

FIG.14




FIG.15




FIG.16






FIG.17




FIG.18





FIG.19



0942663.11501

FIG. 20




FIG.21




FIG.22





FIG.23







FIG.24



FIG.25



1.09T.T. E9924660

FIG.26

